



*MaxFlight Corporation  
1 Executive Drive  
Toms River, NJ 08755, USA  
+1(732)281-2007  
FAX +1(732)281-2009  
[www.maxflight.com](http://www.maxflight.com)*

**Mandatory!**

**SERVICE BULLETIN: SB111099, Pitch Shaft Plugs**

FROM: MAXFLIGHT CORPORATION  
FAX: 732-281-2009  
VOICE: 732-281-2007 x 222

**MESSAGE:**

Affects all simulators manufactured by MaxFlight Corporation.

Pitch Shaft Plugs with hardware must be installed on all MaxFlight Simulators manufactured prior to November 10, 1999.

**INSTRUCTIONS:** Call MaxFlight Technical Support at 732-281-2007 x 222 to place an order for pitch shaft plugs referencing this service bulletin. After order and instructions are received, install them on the unit.

Non-compliance of Service Bulletins adversely affects warranty and liability issues.

Please confirm receipt of this SERVICE BULLETIN by faxing this cover page with your signature on bottom line to MaxFlight Corporation at +1(732) 281-2009 within two days.

**Signature**

**Company**

---

---