



*MaxFlight Corporation
1 Executive Drive
Toms River, NJ 08755, USA
+1(732)281-2007
FAX +1(732)281-2009
www.maxflight.com*

MANDATORY!

SERVICE BULLETIN: SB 120606, Passenger Restraint System

FROM: MAXFLIGHT CORPORATION
FAX: 732-281-2009
VOICE: 732-281-2007 X 235

MESSAGE:

Affects all hydraulic and electrical simulators manufactured by MaxFlight Corporation.
We no longer support simulators that have shoulder harness release system from older versions.
They are:

1. Electrical drive system to close/open the shoulder harness.
2. Hydraulic locking/release system.
3. Bloc O-lift systems, that used a cable to lock/release the gas strut duck bill, of the shoulder restraint system.

NEW VERSION: Consists of replacing any existing system with a new shoulder harness pivot bolt, new gas strut assembly, crotch belt assembly using over 90 degree release buckles and sensor switches, that when shoulder harness are released, stops the ride instantly to the home level position.

INSTRUCTIONS: For complete parts required and installation instructions go to internet access and type in www.maxflight.com, click on "SUPPORT", click on the machine model you have. Look for "Latest Documentation" and download PDF file of "Shoulder Harness Upgrade".

Or, call MaxFlight Technical Support at 732-281-2007 ext 222 and ask for either e-mailed or mailed copy of instruction package. Hours of operation are from 0800 to 1700 hrs, Monday to Friday, Eastern Standard Time.

Please confirm receipt of this SERVICE BULLETIN by faxing this cover page with your signature on bottom line to MaxFlight Corporation at +1 (732) 281-2009 within two days.

Signature

Company
