



MaxFlight Corporation
1 Executive Drive
Toms River, NJ 08755-4947 USA
+1 (732) 281-2007
fax +1 (732) 281-2009
www.maxflight.com

SERVICE BULLETIN

TO: Wayne Brandon **FROM:** Lana Gruzinova
FAX: 01253 4010198 **FAX:** 1(732)281-2009
COMPANY: Blackpool Pleasure Beach **VOICE:** 1(732)281-2007
SUBJECT: MaxFlight Service Bulletin# SB082802 **PAGES:** 1
SENT: April 8, 2004

Please Pass to your Technical Department

This Service Bulletin Affects all MaxFlight Units with the Bloc-O-Lift Restraint System Installed.

It is required to replace the Nylon Bushings and Grade 8 Bolts for the upper clevis with the following
P/N: 12034-Brass Bushing - \$2.50 each (4 are required) 2 per lap bar
P/N: 11638M-1/2-13 Bolt and Washer - \$10.80 each (2 are required) 1 per lap bar

If your upper clevis has not been up-graded to the style with a set screw, you should order
P/N: SE22003-Upper Clevis-\$12.60 each (2 are required) 1 per lap bar

This system is required to be changed as soon as possible. You must submit a Purchase Order, faxed to 732-281-2009, if you have a shipping account with UPS, DHL, or FedEx, please include the account number, this will expedite the shipmnets. We have limited quantity on hand, but will be replenishing stock as quicley as possible.

*Thank you for your attention to this matter.
MaxFlight Technical Department.*

IMPORTANT

Please CONFIRM RECEIPT of Service Bulletin by faxing signed cover sheet to MaxFlight Corporation at 1(732)281-2009 within two days.

URGENT

Signature (confirming receipt)